	Labels of class 1	i	1.4	1.5	1.6
	Labels of class 2	2	2	2	•
	Labels of class 3	3	3	v	
	Labels of class 4				
	Labels of class 5	OZIDIZE S	ORGANIC PEROLIDE		
5	Labels of class 6	6	BFECTIOUS SUBSTANCE		
	Labels of class 7	RADOACTIVE I	RADIOACTIVE	RADIOACTIVE III	FISSILE
	Labels of class 8				
	Labels of class 9				
	MARINE POLLUTION MARK	¥2>			
	ELEVATED TEMPERATURE MARK				
)	FUMIGATION WARNING SIGN	DANGER THIS UNIT IS UNDUR FUMOUTON WITH OWNER OUTE TAME VENTEATED ON: DO NOT ENTER			